

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2011 Levee Inspection Results**

**Reclamation District No. 2101 Blewett**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 2101 Blewett**

Waterway			Bank	Unit Miles
Unit No. 01 San Joaquin River			Left	3.20

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/26/2011 - 5/26/2011			
DWR Inspector	Jim Eto			
Accompanied By	Jim Coddington RD 2101		Jim Coddington RD 2101	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River				Left	3.20	05/26/2011 05/26/2011	Jim Eto

  

LMIR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
1	0.02	0.72	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	37.657521 ° -121.254203 °	37.659868 ° -121.244029 °	3
2	0.02	2.75	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: 05/26/2011 Excessive vegetation growth on the waterside slope for the full length of the unit. LMA has stated that he is not allowed to spray and perform proper vegetation control due to restrictions imposed by Department of Fish and Game.	37.657521 ° -121.254203 °	37.641882 ° -121.229713 °	2 Y
3	0.02	2.75	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: 05/26/2011 Excessive vegetation growth on levee slopes for the entire length of the unit.	37.657521 ° -121.254203 °	37.641882 ° -121.229713 °	32 Y
4	0.13	0.13	Earthen Levee	Animal Control	CR	M	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: 05/26/2011 Rodents are visible in newly harvested field, burrows are not visible because of vegetation growth on the slopes.	37.657291 ° -121.252605 °	37.657291 ° -121.252605 °	4
5	0.17	0.17	Earthen Levee	Animal Control	CR	M	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: 05/26/2011 Rodents are visible in newly harvested field, burrows are not visible because of vegetation growth on the slopes.	37.656892 ° -121.252109 °	37.656892 ° -121.252109 °	948
6	0.19	0.19	Earthen Levee	Encroachments	CR	W	Pipe	37.657128 ° -121.251692 °	37.657128 ° -121.251692 °	7 Y
7	0.19	0.30	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	37.657028 ° -121.251817 °	37.658001 ° -121.250269 °	6
8	0.49	0.49	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: Last Fall, Fish & Game stated they would now allow vegetation maintenance on water side. Improvements are being made. 05/26/2011 LMA is not aware of this, it is his understanding that vegetation management is still NOT allowed per DFG on the waterside.	37.660007 ° -121.248065 °	37.660007 ° -121.248065 °	5 Y
9	0.59	0.67	Earthen Levee	Seepage / Sandboils	LS	U	Inspector Comments: 05/26/2011 Picture shows field damaged by water from seepage.	37.660029 ° -121.246400 °	37.659956 ° -121.244706 °	31 Y
10	0.73	0.73	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Wild Rose has been trimmed back some.	37.659856 ° -121.243806 °	37.659856 ° -121.243806 °	9
11	0.74	1.34	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	37.659805 ° -121.243678 °	37.653223 ° -121.238531 °	17

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 San Joaquin River						Left	3.20	05/26/2011 05/26/2011	Jim Eto	
LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
12	0.76	1.80	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	37.659827 ° -121.243675 °	37.651049 ° -121.231475 °	944 Y
13	0.76	0.76	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.659723 ° -121.243384 °	37.659723 ° -121.243384 °	10
14	0.86	0.86	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.658733 ° -121.241944 °	37.658733 ° -121.241944 °	11
15	0.91	0.91	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.658432 ° -121.241344 °	37.658432 ° -121.241344 °	12
16	1.35	1.35	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	37.653066 ° -121.238162 °	37.653066 ° -121.238162 °	951
17	1.36	1.60	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	37.653085 ° -121.238216 °	37.651508 ° -121.234595 °	18
18	1.40	1.40	Earthen Levee	Crown Surface / Depressions / Rutting	WS	C	Regrade the crown roadway for proper drainage. Inspector Comments: Several lateral cracks have appeared on levee crown. They've since been covered by grading.	37.652835 ° -121.237586 °	37.652835 ° -121.237586 °	952
19	1.61	1.82	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	37.651566 ° -121.233688 °	37.650822 ° -121.230702 °	15
20	1.61	1.61	Earthen Levee	Encroachments	WS	W	Pipe Inspector Comments: Pipe penetrates through levee. Closure valve on water side slope.	37.651552 ° -121.234346 °	37.651552 ° -121.234346 °	13 Y
21	1.62	1.84	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.651574 ° -121.234326 °	37.650748 ° -121.230342 °	26 Y
22	1.63	1.63	Earthen Levee	Encroachments	LS	PO	Poles	37.651555 ° -121.234061 °	37.651555 ° -121.234061 °	14
23	1.83	1.99	Earthen Levee	Encroachments	WS	C	Agricultural tilling Inspector Comments: Discing near levee slope within 10' of levee toe.	37.649811 ° -121.228047 °	37.649811 ° -121.228047 °	16
24	1.85	2.61	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	37.651508 ° -121.234595 °	37.643625 ° -121.229221 °	22
25	1.91	2.00	Supplemental	DWR Erosion Survey	WS	U	Inspector Comments: 05/26/2011 Damaged area now encroaches into the levee prism, Photo has been provided by LMA, photo taken during high water. Thick thistle growth prevented access to take current picture on day of inspection.	37.650259 ° -121.228961 °	37.650259 ° -121.228961 °	1 Y
26	1.91	2.00	Earthen Levee	Seepage / Sandboils	LS	U	Inspector Comments: 05/26/2011 LMA reports that seepage was occurring through Erosion survey site, causing damage to adjacent field.	37.650259 ° -121.228961 °	37.650259 ° -121.228961 °	8 Y

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway					Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River					Left	3.20	05/26/2011 05/26/2011	Jim Eto

  

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
27	2.04	2.04	Earthen Levee	Crown Surface / Depressions / Rutting	CR	C	Regrade the crown roadway for proper drainage. Inspector Comments: Dips in the road at 30-ft intervals could be due to lateral cracking in the levee and/or shallow animal burrows. The road is graded annually to smooth road surface but subsurface condition is unknown.	37.649547 ° -121.227316 °	37.649547 ° -121.227316 °	954
28	2.06	2.06	Earthen Levee	Animal Control	CR	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.649382 ° -121.226997 °	37.649382 ° -121.226997 °	955
29	2.62	2.62	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	37.643531 ° -121.229398 °	37.643531 ° -121.229398 °	19
30	2.66	2.66	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	37.643080 ° -121.229905 °	37.643080 ° -121.229905 °	20
31	2.74	2.74	Earthen Levee	Encroachments	WS	W	Pipe	37.642005 ° -121.229742 °	37.642005 ° -121.229742 °	21 Y
32	2.85	3.20	Earthen Levee	Vegetation	LS	C	Remove the wild growth other than native grasses from the levee slopes.	37.640726 ° -121.230235 °	37.637066 ° -121.233780 °	23
33	2.88	2.88	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.640305 ° -121.230095 °	37.640305 ° -121.230095 °	27 Y
34	2.89	2.89	Earthen Levee	Encroachments	WS	W	Pipe	37.640133 ° -121.230037 °	37.640133 ° -121.230037 °	25 Y
35	2.89	2.89	Earthen Levee	Animal Control	LS	U	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Numerous rodent holes throughout levee slope.	37.640134 ° -121.230019 °	37.640134 ° -121.230019 °	28 Y
36	2.91	2.91	Earthen Levee	Erosion / Bank Caving	WS	M	Schedule repair of erosion site prior to the next inspection.	37.639852 ° -121.229980 °	37.639852 ° -121.229980 °	29 Y
37	2.91	2.91	Earthen Levee	Encroachments	WS	W	Pipe	37.639824 ° -121.230005 °	37.639824 ° -121.230005 °	24 Y
38	2.95	3.20	Earthen Levee	Encroachments	CR	M	Agricultural tilling Inspector Comments: 05/26/2011 Road is still soft, but is now drivable.	37.639399 ° -121.230384 °	37.637066 ° -121.233780 °	30 Y

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	05/26/2011 05/26/2011	Jim Eto

Levee Mile Report Line	2
Start Levee Mile	0.02
End Levee Mile	2.75
Location	Water Side
Category	Earthen Levee
Item	Vegetation
05/26/2011 Vegetation growth is typical for waterside slopes for the entire length of the unit. LMA has stated that DFG restrictions will not allow him to spray or perform proper vegetation control on the waterside of the levee.	
jeto_s_20110527_529.jpg	



Levee Mile Report Line	3
Start Levee Mile	0.02
End Levee Mile	2.75
Location	Land Side
Category	Earthen Levee
Item	Vegetation
05/26/2011 Vegetation growth is typical of landside slope for the entire length of the unit.	
jeto_s_20110527_528.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.19
End Levee Mile	0.19
Location	Crown
Category	Earthen Levee
Item	Encroachments
Drainage discharge under levee crown.	
jeto_s_20110301_278.jpg	

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	05/26/2011 05/26/2011	Jim Eto

Levee Mile Report Line	8
Start Levee Mile	0.49
End Levee Mile	0.49
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Trees on top 20-ft of waterside slope block access and visibility.

jeto\_s\_20110301\_277.jpg



Levee Mile Report Line	9
Start Levee Mile	0.59
End Levee Mile	0.67
Location	Land Side
Category	Earthen Levee
Item	Seepage / Sandboils

05/29/2011 Discolored field is a result of sitting water from through seepage. Seepage is through a previously repaired portion of the levee.

jeto\_s\_20110527\_530.jpg



Levee Mile Report Line	12
Start Levee Mile	0.76
End Levee Mile	1.80
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Concrete ditch near landside toe.

jeto\_s\_20110301\_292.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	05/26/2011 05/26/2011	Jim Eto

Levee Mile Report Line	20
Start Levee Mile	1.61
End Levee Mile	1.61
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Photo of pump in background and CMP riser with valve in foreground.

jeto\_s\_20110301\_279.jpg



Levee Mile Report Line	21
Start Levee Mile	1.62
End Levee Mile	1.84
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Trees on top 20' of waterside slope obstruct access and visibility.

jeto\_s\_20110301\_287.jpg



Levee Mile Report Line	25
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Looking downstream at a section of the erosion site where scouring caused by an eddy has occurred.

jeto\_s\_20110301\_273.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	05/26/2011 05/26/2011	Jim Eto

Levee Mile Report Line	25
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Looking downstream at the 100-ft long scour.

jeto\_s\_20110301\_274.jpg



Levee Mile Report Line	25
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Looking upstream at the scour site.

jeto\_s\_20110301\_275.jpg



Levee Mile Report Line	25
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Looking upstream at the scour site.

jeto\_s\_20110301\_276.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	05/26/2011 05/26/2011	Jim Eto

Levee Mile Report Line	25
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Updated photo provided by LMA. Looking downstream at scour area. Note that bushes in photo from 12/16/2010 are now gone.

jeto\_s\_20110603\_535.JPG



Levee Mile Report Line	26
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Land Side
Category	Earthen Levee
Item	Seepage / Sandboils

05/26/2011 Field which had crop damage due to sitting water from seepage through erosion control site.

jeto\_s\_20110527\_532.jpg



Levee Mile Report Line	31
Start Levee Mile	2.74
End Levee Mile	2.74
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Irrigation intake near Maze Blvd.

jeto\_s\_20110301\_281.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	05/26/2011 05/26/2011	Jim Eto

Levee Mile Report Line	33
Start Levee Mile	2.88
End Levee Mile	2.88
Location	Water Side
Category	Earthen Levee
Item	Animal Control

Rodent holes on levee slope hidden by vegetation.

jeto\_s\_20110301\_288.jpg



Levee Mile Report Line	34
Start Levee Mile	2.89
End Levee Mile	2.89
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Risers on waterside berm and risers along road leading to levee indicate presence of pipe penetration.

jeto\_s\_20110301\_286.jpg



Levee Mile Report Line	35
Start Levee Mile	2.89
End Levee Mile	2.89
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Rodent holes on levee slope.

jeto\_s\_20110301\_289.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	05/26/2011 05/26/2011	Jim Eto

Levee Mile Report Line	35
Start Levee Mile	2.89
End Levee Mile	2.89
Location	Land Side
Category	Earthen Levee
Item	Animal Control

05/26/2011 Updated photo of animal control issue noted in Fall 2010 inspection, fresh rodent burrow present.

jeto\_s\_20110527\_531.jpg



Levee Mile Report Line	36
Start Levee Mile	2.91
End Levee Mile	2.91
Location	Water Side
Category	Earthen Levee
Item	Erosion / Bank Caving

Levee slope is being eroded at this location. Repair needed to preserve access road.

jeto\_s\_20110301\_290.jpg



Levee Mile Report Line	37
Start Levee Mile	2.91
End Levee Mile	2.91
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Drainage discharge to San Joaquin River.

jeto\_s\_20110301\_285.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	05/26/2011 05/26/2011	Jim Eto

Levee Mile Report Line	38
Start Levee Mile	2.95
End Levee Mile	3.20
Location	Crown
Category	Earthen Levee
Item	Encroachments
Discing of crown roadway surface limits accessibility.	
jeto_s_20110301_291.jpg	

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected/Rated

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 2101 Blewett**

Waterway			Bank	Unit Miles
Unit No. 02 San Joaquin River (Spur Levee)			Right	0.31
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/26/2011 - 5/26/2011			
DWR Inspector	Jim Eto			
Accompanied By	Jim Coddington RD 2101			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River (Spur Levee)	Right	0.31	05/26/2011 05/26/2011	Jim Eto

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.30	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.659774 ° -121.243522 °	37.663866 ° -121.242869 °	1 Y
2	0.00	0.30	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	37.659774 ° -121.243522 °	37.663866 ° -121.242869 °	3 Y
3	0.31	0.31	Earthen Levee	Erosion / Bank Caving	WS	M	Schedule repair of erosion site prior to the next inspection. Inspector Comments: At the end of this spur two rivers converge and due to past high water events a large scour hole has been formed. It is now filled in with vegetation. The next HW event could further scour this large hole. 05/26/2011 scour hole still present, no change,	37.663998 ° -121.242925 °	37.663998 ° -121.242925 °	2

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2101 Blewett**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River (Spur Levee)	Right	0.31	05/26/2011 05/26/2011	Jim Eto

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.30
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Tall weeds on levee slope obstruct visibility.

jeto\_s\_20110301\_293.jpg



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.30
Location	Water Side
Category	Earthen Levee
Item	Vegetation

05/26/2011 Photo shows typical vegetation for the entire length of the spur levee.

jeto\_s\_20110527\_534.jpg



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.30
Location	Land Side
Category	Earthen Levee
Item	Vegetation

05/26/2011 Photo shows typical vegetation for the entire length of the spur levee.

jeto\_s\_20110527\_533.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor